Indriect Area study in Tyre Manufacturer Industry.

About the Client

- Client is a manufacturer & supplier Automobile 2 and 3-wheeler Tyres.
- Client's vision is to be the global leader with a vision to make mobility, safer and smarter.

Aims/Objectives

- Work content measurement using time study on sample basis for Indirect area.
- Work Distribution for manpower utilization.
- Resource calculations i.e., manpower as well as machines.
- Lean wastes analysis.

Key Points

- Productivity improvement by 60%.
- Workforce reduction by 37%.
- Increased workforce utilization to 84.2% from 66.6%.

Client's Challenge

- Standardization of work content based historical data and client site data.
- Muda & Muri analysis for further improvement.
- Identify true Manpower requirement of plant.

PMI's Approach

The study was organized in a 3-stage process:

- 1. Data Collection
 - a. Plant round to understand the scope of work.
 - b. Interaction with respective area owners/executives to understand the various activities carried out in the area.
 - c. Data requirement sent to area owners for logs of various activities.
- 2. Estimation & Data Analysis Time/stopwatch study done on sample basis for some activities, work distribution, Resource Calculation, Lean waste analysis.
- Results and Conclusion –Improved productivity, improved manpower utilization, identification of NVA work content.

Involvement of Associates -

- PMI 1 Project Manager, 2 Engineers.
- Client 1 Project Co-ordinators, Area Managers of various areas and some Associates.

Data Collection-

- Plant round to understand the scope of work.
- Interaction with respective area owners/executives to understand the various activities carried out in the area.
- Data requirement sent to area owners for logs of various activities.
- Receiving Logs of Breakdowns, Preventive Maintenance activities and other activities such as Daily
 activities, Tests carried out in QA labs for last 6 months, also some other activities such as Time and
 Condition based Monitoring list from client.
- Interaction with client to understand documents and processes.

letk.	0AT	281	88	NACHINE NO.	387.002	PHENOMENON	PHENOLA PREMIMENCIN	CAUSE	ACTOR	TOTAL TRAUMAD	TMERSI	No.ef.
u.	61-05-2025	c	MCC	MCC-DD	UNS .	OFFICE NOT START	SQUEEZE PRESSURE DION'T APPLY IN C4	DIS MOULD UNEVEN UP CONIN HAPPENING	RELATED PARAMETERS CHECKED	15.00	0.25	
	61-05-2025	A	MCC	MCC-27	а	STACKING HEIGHT VARIATION	LIVET NOT WORKING	BRASS BUSH SZAL LEHINAZ	BRADE BUSH SEAL CHINIGED	25.00	0.42	30
1	01-05-2025	*	MCC	MCC-29	- 13	STICKING HEIGHT VARIATION	CENTERPOST LP-DOWN NOT INFPENING	CP CILINDER BYRADZD	CP CILINDER REPAIRED AND REVETING DOME	90.00	0.85	20
	01-05-2025	к	MCC	MCC-40	Q	C M CLAMP BOLT LOOSE	THE UP COMINING FARMENING	CM CYLINDER C-CLAMP WELDING REMOVED	C CLAMP WELDING DONE	255.00	5.82	94
1	01-05-2025	c	MCC	MCC-53	US	NED A FALLAURM	CILIC PRESSURE LATE PLOX-UP	RTD POSITION WKG CHANGED	RTD-POSITION CHANGED (REVERTED TO PREVIOUS SIDE)		1.75	42
	01-05-2025	c	105	RUNDUT-25	MADIA	PHILTIAL MINIE ON TYPE	MARKING NOT DONE PROPERLY ON TYPE	MARKER POINTER DISINGER CHUCK NUT REMONED	CHUCK NUT TO TRAITENING DOME		0.33	
u -	63-65-2025		MCC	MCC-04	US	NED A FALLAURM	INTERNAL TEMPERATURE NOT PICK-UP ALARM COMING	RTD POSITION WKG DWWG2D	RTD POSITION CHANGED (REVERTED TO PREVIOUS SIDE)	25.00	0.42	30
1	63-65-2025	c	MCC	MCC-SD	a	STICCING HEIGHT VARIATION	L-SECTION REMOVED	MOUNTINE BOLT THREED WASH OUT	L-SECTION RE-FITTING DOME		0.58	- 14
u –	63-65-2025		MCC	MCC-42	a	STICKING HEART VARIATION	HECTON REMOVED	MOUNTING BOLT THREED WASH OUT	ORILLING & TAPPING AND NEW BOLT RE-FITTING DONE		0.82	22
	02-05-2025	мыс	MCC	MCC-HS	86	NOULD UNEXEN OPEN-CLOSE	MOULD UNEVEN OPEN-CLOSE	NO REASON FOUND	MOULD OPEN-CLOSE FLOW ADJUSTED BUT PROBLEM CONTINUED		0.83	20
4	42-09-2023	c	MCC	M00-51	Q	STICKING HEIRIT VARIATION	LISECTION REMOVED	MOUNTING BOLT THREED WASH OUT	LARCTION REFETTING DOME	25.00	0.42	50
4	42-68-2028	c	MCC	MCC-58	145	NED A FAIL ALARM	INTERNAL TEMPERATURE AND PRESSURE NOT PICE-UP	NO REASON FOUND	HPS CONTROL VALUE OPERATION CHECKED	35.00	0.58	14
4	42-69-2023		900	502-50	64	STICKING HEIGHT VARIATION	THE UP OOWNINGT HIPPENING	TYRE LIFT CYLINGER STUCKED IN UP CONDITION	MANUK, OPERATION DONE, MICHINE STAFTED UNDER OBSERVATION		0.42	50
	41-09-2028	46	sec	900-11	08.04	UNDERCURE	TREAD UNDER CURE REPORTED	PLATENLINE MODIFICATION DONE THERE IN FREVOUS SHIFT (NRV AND RTD INSTALLATION)	PLATENUME NRV BIPASSED	290.00	4.83	116
	Pň	TON	Daily_Log	jbook	+							

Breakdown Logs

Data Analysis -

- Preparation of activities work content by time study and validation by client.
- Analysis (Work distribution/VA-NVA identification) for manpower calculation, optimum manpower utilization.
- Improvement & suggestions for reducing Lean wastes and making existing system better.

					Daily	Work Content (in r	nins)	NVA- N Activiti	on Value es	e Added	
ŝr no	Activity	Sub-Activity	Category	Existing WC (in mins)	Daily WC (in mins) (Existing)	Existing WC (in mins) (After validation)	Daily WC (in mins) (NVA Removal)	Waiting	Tool	Talking	Remarks
1	Curing First tyre		Curing FTC	45	1080.00	1080.00	720.00	360.00	0	0	1. Approval time - 15 min waiting. (Manager, Moul shop engineering, Proces Associate) 2. (8-10/shift)
2	Pending FTC		Curing FTC	30	720.00	720.00	600.00	120.00	0	0	1. Movement time -5 mir 2. (8-10/SHIFT)
3	Curing last tyre check		Curing LTC	30	720.00	720.00	600.00	120.00	0	0	1. Need 6 month log (8- 10/SHIFT)
3	Mould grading for ICE blasting		Grading	15	300.00	300.00	300.00	0.00	0	0	1. 20-25 logs/day
4	Curing mould inspection	1. Going from CFT to MCC 81 press	Inspection	3	4.68	4.68	4.68	0.00	0	0	1.60-70 curing mould inspection
4	Curing mould inspection	2. Checking tyre and check sheet filling for 1 cavity	Inspection	10	15.60	15.60	15.60	0.00	0	0	1.60-70 curing mould inspection
4	Curing mould inspection	3. Abnormality identification, communication & correction	Inspection	10	7.96	7.96	7.96	0.00	0	0	1.60-70 curing mould inspection
5	Curing process audit	1. Going from CFT to curing press	Process Audits	2	9.42	9.42	9.42	0.00	0	0	
5		2. Parameter check in HMI, PCI, and each cavity	Process Audits	30	141.30	141.30	94.20	47.10	0	o	1. 10 mins waiting time d to cycle (communication with coordinator can solution the problem
5	Curing process audit	3. Abnormality identification, communication & correction	Process Audits	15	35.33	35.33	35.33	0.00	0	0	
6	TBM Route card	1. Going from CFT to building	Documentation	2	16.00	16.00	16.00	0.00	0	0	1.8-10 frq per day (Only OEM no Replacement)
6	TBM Route card	2. Parameters checks regarding drum, material cantering and	Documentation	23	184.00	184.00	144.00	40.00	0	0	1.8-10 frq per day (Only OEM no Replacement) 2.5 MINS (nva_WAITING


Sample Analysis of Process Audit area

Results & Conclusion

After doing analysis and evaluation following results were obtained -

1. Improved productivity by 60%.





Contact Details

Name of Organisation	Production Modelling India, Nagpur				
Contact Name	Pavan Nikhare				
Email Address	pnikhare@pmcorp.com				
Website	www.pmicorp.in				